
MI 12 interface unit

The MI 12 interface processes signals between one or two OMM's and the CNC machine control.

(The MI 12 replaces the earlier MI 4 and MI 7 interface units)



System status

System status is presented visually in a continuously updated form, on the front panel diagnostic LED display, and by outputs available from the MI 12 to the CNC machine control.

1. Audible indicator (bleeper)

The speaker is behind the front panel.

2. Error LED

Lit when optical beam obstructed, probe out of range, probe switched off, etc.

3. Low battery LED

Replace probe batteries as soon as practicable, after this LED lights up.

4. Probe status LED

Lit when probe is seated.

Off when stylus is deflected or an error has occured.

5. Power LED

Lit when power is on.

6. Start button - switch SW1

Manual start push button. Press button to switch system to operating mode. Normally a machine start or auto start signal is used.

Machine start/Auto start options

A software command from the CNC control initiates probe system switch-on (machine start).

Alternatively an internal MI 12 switch may be set to the auto start mode, which causes the OMM to send a start signal once every second, and activate the probe prior to an inspection routine.

Factory set to machine start.

The MI 12 interface is available as:

1. MI 12 interface unit

The interface board is contained within a free standing enclosure. The optional panel mounting kit, provides for attachment to the machine cabinet.

2. MI 12-B

Board only for mounting within the machine cabinet, using self adhesive feet or M4 support studs.

Outputs from MI 12

There are four solid state relay (SSR) outputs, comprising probe status and skip complimentary outputs - selected by an internal switch, an error output and a low battery output.

The output signals from the interface must be compatible with the machine control intput.

Maximum current ±40mA peak.

Maximum voltage ±50V peak.

Remote audible indicator or lamp

There is one output for a remote audible indicator or lamp (not supplied by Renishaw), which is used when the MI 12 is remote from the machine operator. The output will sink 100mA and should have no more than +50V DC applied to it. The output will remain active for 44ms after each probe change of state.

Power supply

The MI 12 can draw its supply from the CNC machine +15 to 30V DC and presents a load of up to 400mA. Alternatively the Renishaw PSU3 power supply unit supplies power, when a 24V supply is not available from the machine control.




DATA SHEET

Installation


dimensions mm (inches)

Panel mounting

The interface unit may be mounted inside the CNC machine cabinet, using the optional panel mounting kit. Holes must be cut in the machine protective panel to accept the MI 12 front panel and fixing screws as shown in diagram below.



A. Four countersunk holes



MI 12 terminal connections

- SIGNAL
- SIGNAL 1 2
- START 1 3
- 4 0V
- 5 10V
- 6 ٥V
- 7
- SIGNAL 2 8
- START 2 9
- 10 **ERROR** SSR 11
- 12
- LOW BATT 13 SSR
- 14 PROBE STATUS SSR 15
- +24V SUPPLY 16
- **0V SUPPLY** 17
- 18
- SIGNAL STRENGTH OMM 1
- 19 20 **AUDIO EXTENSION**
- 21 MACHINE
- START
- 22 -ve
- PROBE STATUS 23
- SSR 24

OMM signal strength test points T1, T2 and T3

Test points are located on the MI 12 printed circuit board (PCB). Signal strength is measured using a digital volt meter (DVM).

OMM 2

Minimum receivable signal approximately 0.36V DC. Maximum signal strength output approximately 7V DC.

OMM₁

Signal strength levels same as T1. (Also available on terminal 19).

0V reference.

Parts List - Please quote the Part No. when ordering equipment

152 (5.98)

Туре	Part No.	Description	
MI 12	A-2075-0142	MI 12 Interface Unit.	
MI 12-B	A-2075-0141	MI 12 Interface Board only.	
Panel kit	A-2033-0690	Panel mounting kit for MI 12 interface unit.	
Fuse 62mA	P-FS20-0062	62mA (T) quick blow fuse	FS1 (spare), FS2 - Error, FS3 - low battery,
			FS4 - probe status N/C, FS6 - probe status N/O.
Fuse 250mA	P-FS20-1A25	250mA (T) anti-surge fuse	FS5 - audio extension protection.
Fuse 500mA	P-FS01-1A50	500mA (T) anti-surge fuse	FS7 - power supply protection.

Renishaw plc

9

6,5

New Mills, Wotton-under-Edge, Gloucestershire, GL12 8JR, UK +44 (0)1453 524524 [07000 RENISHAW] Fax +44 (0)1453 524901 Telex 437120 RENMET G email uk@renishaw.com

RENISHAW

www.renishaw.com

+1 847 286 9953 +1 847 286 9974 email usa@renishaw.com

76 (2.99)

Renis haw K.K., Japan +81 3 5332 6021 +81 3 5332 6025 email japan@renishaw.com

aw GmbH, Germany +49 7127 9810 +49 7127 88237 germany@renishaw.com

Renishaw S.A., France +33 1 64 61 84 84 +33 1 64 61 65 26 france@renishaw.com Renishaw S.p.A., Italy Tel +39 011 9 66 10 52 +39 011 9 66 40 83 italy@renishaw.com aw Iberica S.A., Spair +34 93 478 21 31

Tel +34 93 478 16 08 spain@renishaw.com aw A.G., Switzerland +41 55 410 66 66

+41 55 410 66 69 switzerland@renishaw.com Renishaw Latino Americana Ltda..

+55 11 4195 2866 Tel +55 11 4195 1641 Renishaw reserves the right to change specifications without notice Renishaw (Hong Kong) Ltd., Hong Kong, The People's Republic of China

+852 2756 8786 hongkong@renishaw.com Renishaw Metrology Systems

Private Limited, India

+91 80 5230 144 +91 80 5230 140 email india@renishaw.com

Renishaw Oceania Pty Ltd., Australia

Tel +61 3 9553 8267 australia@renishaw.com

Part No. H-2000-2195-02-C

Indonesia Tel +62 21 428 70153

+62 21 424 3934 indonesia@renishaw.com email Tel +65 897 5466

singapore@renishaw.com email Tel +886 4 251 3665 +886 4 251 3621 email taiwan@renishaw.com

pple's Republic of China +86 10 641 07993 +86 10 641 07992

china@renishaw.com Renishaw's Liaison Office

+82 2 565 6879 southkorea@renishaw.com