



[New](#) [Closed](#) [Wish](#) [Info](#) [Admin](#) [ViewAll](#) [Search :](#)

QC	98 : Support multiple Heidenhain alignment styles	24/12/2009
	92 : Need to be able to configure multiple machines in one NC-Connector	13/10/2009
JSC	91 : We need to convert the ATEKs into proper installs	02/10/2009
3.01.10 PB	90 : Crash when dealing with long (259+ chars) strings in the command window	15/10/2009
	86 : Siemens needs ability to output a tapefile	08/10/2009
	85 : Mazak probe calibration automation	29/09/2009
	84 : Mazak needs 5 axis support	23/07/2009
	78 : We have no ncconnector for the fanuc	22/02/2010
	73 : Siemens 840D needs to be completed	08/10/2009
	67 : Bouncing ball could be shown by serial port pages	08/10/2009
	64 : Mazatrol Matrix: Load/Unload programs	01/10/2009
JSC	55 : The ATEK perl out2msr.pl has a serious bug when noshow is used on NEXT page	01/10/2009

11 items outstanding

with 1 awaiting QC

with 1 scheduled items