

## Shank modifications for machine tool probes


The following modifications can be made to various types of shank, for example DIN69871, BT, HSK etc. For details of available shanks, see data sheet H-2000-2011 or contact your Renishaw supplier.

Please consider the layout of the machine tool before modifying the shank; for example, ensure that fittings on the spindle housing do not obstruct access to the screws in the shank nose.

For details of individual probes, refer to the relevant data sheet.


## The drawing below shows how to adapt shanks for the following probes:

- OMP60
- RMP60
  Dimensions in mm (inches)
- MP11



## The drawing below shows how to adapt shanks for the following probes:

- OMP40
- OMP400
- MP20



Ø4.5 MAX. TO LEAVE 8 MM MIN.

FULL THREAD.)



Ø4.5 MAX. TO LEAVE 8 MM MIN.

FULL THREAD.)