

[New](#) [Closed](#) [Wish](#) [Info](#) [Admin](#) [ViewAll](#) [Search :](#)

ncconnector

	187 : Engineer mode to allow debugging	22/08/2012
	186 : ATEKHSPlus: Automatically FTP to the controller	22/08/2012
	185 : Siemens: Incorrect file extension when relocating MPF files	17/08/2012
QC	184 : Siemens: Offline mode not supported by IO_PutSync	14/08/2012
QC	183 : Fanuc: Code not as efficient as it could be	14/08/2012
	182 : Fanuc: Screen While Waiting for Results is Blank.	26/07/2012
QC	181 : Heidenhain: Add a new subroutine for uploading file	24/07/2012
QC	180 : Heidenhain: Improve error handling	24/07/2012
	179 : AI: Add reflection validation for uploaded files	13/07/2012
	178 : Heidenhain: TNCcmd should be made relative or the option removed	06/07/2012
QC	177 : Heidenhain: TNCcmd should be included	27/06/2012
	176 : Siemens: Macro validate does not create directory structure	01/06/2012
	175 : ATEK: Process triggering not possible	22/05/2012
	174 : FANUC: Better synchronise the start of the program	22/05/2012
QC	173 : Remove redundant implementations directory	25/05/2012
	172 : Fanuc: UploadFile.xml should set the background directory	14/05/2012
QC	171 : Fanuc: IO_GetMSR does not start the JVM	25/05/2012
QC	170 : AI: Need a new task IO_PutDatum	25/05/2012
QC	169 : Siemens: Dubious code in hole offset plugin	25/05/2012
	168 : FANUC: MSR Letter address to hash register mapping is in two places	14/05/2012
	167 : FANUC: Need new fields and mods to programs	23/05/2012
	163 : AI: Display a more elegant file watcher	03/05/2012
	150 : Mazatrol: IO_PutAlign should not upload in offline mode	23/12/2011
	148 : Siemens: Implement IO_PPToTape	20/12/2011
	144 : Siemens: Time limit an MSR load	23/08/2011
JSC	140 : AI: Tidy configuration use of variables to avoid duplication	22/08/2012
	134 : Siemens: Combine toolname *none* and \$SkipStage2	17/10/2011
	129 : Show files should be supported by all NC-Connectors	26/01/2011
	86 : Siemens needs ability to output a tapefile	08/10/2009
	85 : Mazak probe calibration automation	22/06/2010
	84 : Mazak needs 5 axis support	23/07/2009
	67 : Bouncing ball could be shown by serial port pages	08/10/2009
	64 : Mazatrol Matrix: Load/Unload programs	01/10/2009

24 items outstanding

with 9 awaiting QC

ezippcompare

PB	233 : Introduce Quality to the Calibration file	23/08/2012
RAMRSW	232 : Equator CMM compare does not agree with CMM	29/06/2012
	231 : Helical Scan doesn't produce good results in Comparison mode	29/06/2012
	230 : The Command dlg doesn't resize properly	21/06/2012
	228 : ScanOnCircle not running with pass-through data	23/05/2012
PB	227 : Setup blade testing	21/05/2012
	225 : Inform the User when the dll has failed to load	17/05/2012
PB	224 : An Error during a Master Start still sets Master mode to be active	23/05/2012
	222 : Include version number of dll in Exported file	02/05/2012

	214 : ezIPPCompare has been moved	03/02/2012
PB	212 : Load Data from Exported file into ezIPPCompare	25/05/2012
PB	211 : Component is corrected by the Master Error vector instead of the Component's	26/01/2012
	199 : Check for unknown part scans	22/08/2011
	198 : Tag Modification	22/08/2011
	195 : Master Saving doesn't fail until Action(End)	04/08/2011
	194 : Master File saving only works with directories that already exist	04/08/2011
	192 : Data commands don't check for an error state when they receive data	26/07/2011
	191 : Aborting commands that have errors	26/07/2011
	177 : Add unknown volume scans for comparison	01/06/2011
	176 : Investigate the Use of Intermediate points in ScanOnCurve	01/06/2011
	175 : Repeatability of ScanOnHelix	06/07/2011
	173 : Require a Document that details how to export data from the Comparator	06/07/2011
	165 : Should we return an Error for too many invalid points?	08/05/2012
RAMRSW	157 : Make PtMeasSelfCenter a comparable command	01/06/2011
	155 : Add Tests for Loading Master and Calibrate file	20/01/2011
	149 : Diagnostics Reporting	13/12/2010
PB	148 : RWCompare doesn't send '%' until another command is sent	02/11/2011
	135 : Email: Cosine Error	06/07/2011
RAMRSW	125 : Email: ISO 10360	17/08/2010
	106 : Scan On Cylinder cmds and Axis out of plane error	20/04/2010
	104 : Handling OnReport() commands	19/10/2011
	96 : ezIPPCompare doesn't return valid errors	22/08/2012
	92 : Placeholder for analysis reporting	22/07/2010
	81 : Reason for Calibration file loading failure should be clear	09/11/2011
	80 : Add Test for Loading a Calibrate file when no Master is loaded	08/05/2012
	79 : Data point returned after error in PtMeas	08/01/2010
	57 : A Proxy error does not set an error state	27/04/2010
	55 : mspComparator::HandleCommand()'s potential size	27/04/2010
	39 : Error in a SUPPORTED Command should invalidate the Current Comparison	10/08/2009
	38 : No Response from a HANDLED command	12/08/2009
	37 : Performing a Component-Start without Master Data should not be allowed	27/04/2010
	36 : Simplex Fit calculation has an error	07/02/2011
	35 : Memory Leak	27/04/2010
	29 : Clients which send all commands in one go cannot be used	28/07/2009
	23 : Need to implement a mechanism for controlling the contents of the command window	30/06/2009
	19 : Need a mechanism for indicating the state of the data	27/06/2009

46 items outstanding

ariesmill

CS	53 : Move parameters require synchronisation with server	22/08/2012
QC	52 : The ezLinkNC post_build script still attempts to copy mspMill.dll to release directory	20/08/2012
QC	51 : Tool properties can not be applied when no tool is set	20/08/2012
PB	50 : Create an API document	27/07/2012
QC	49 : uccServerInterfaceUtest isn't implemented in ezLinkNC for AriesMill	15/08/2012
QC	48 : UI becomes unresponsive if return or escape keys are pressed	30/07/2012
QC	47 : User is not informed if config file is read-only	24/07/2012
	45 : Sending an AbortE takes a long time to clear the commands an EStop does not	29/06/2012
	44 : Doing a Jog Move has a noticeable delay, Absolute moves do not	29/06/2012
CS	39 : ezLinkNCDoc needs menu initialisation	27/07/2012
CS	38 : Split concept of task and connection	07/06/2012
	27 : A container class is required to wrap the many groupboxes within the Mill UI.	17/05/2012
	26 : Mill UI not updated in some conditions	28/06/2012
	25 : Command throughput	28/05/2012
	17 : Have a generic system for mapping GCode to MachineIO pins	23/01/2012
	16 : Allow multiple instances of AriesMill on one PC	19/01/2012
RAMRSW	14 : Test Jerky Machine movement with latest controller release	16/01/2012
	13 : Coolant Control - M??	12/01/2012
	12 : Tool Changing - M6	12/01/2012

- 11 : Spindle Control M??
- 9 : Circular interpolation G02, G03, G12 and G13

[22/03/2012](#)

[27/07/2012](#)

16 items outstanding

with 5 awaiting QC