Renishaw plc New Mills, Wotton-under-Edge, Gloucestershire GL12 8JR United Kingdom T +44 (0) 1453 524524 F +44 (0) 1453 524901 E UK@renishaw.com www.renishaw.com



## PH10 part number changes for RoHS compliance – OPEN Renishaw CMM products division Product bulletin: PBC-02034

| Product:             | PH10 ra | ange            | Date:                 | 10th March 2017 |                       |
|----------------------|---------|-----------------|-----------------------|-----------------|-----------------------|
| Originator: Nathan F |         | Fielder         | Reviewer:             | Andy Ho         | olding                |
| Classification       |         |                 | Distribution          |                 |                       |
| C Competitor info    |         | O Recall        | ✓ Agents              |                 | <b>☑</b> Distributors |
| O Pricing changes    |         | O Quality issue | ✓ Subsidiaries        |                 | <b>☑</b> End users    |
| O Product hold       |         | C Literature    |                       |                 |                       |
| C Product launch     |         | Obsolescence    | ✓ Service centres     |                 | <b>☑</b> OEMs         |
| Product update       |         |                 | <b>☑</b> Retrofitters |                 |                       |

## **Summary:**

To ensure that Renishaw conforms to the impending RoHS (Restriction of Hazardous Substances) compliance requirements, it has been necessary to introduce a new series of part numbers for the PH10 range of heads. These new part numbers will provide a clear distinction between product that is non-RoHS compliant and product that is RoHS compliant. These part numbers are available for use now and should be used on all future orders. Existing orders will be changed to the new part numbers as appropriate.

For new head orders, four new part numbers will replace the previous part numbers. Only RoHS compliant heads can be ordered for new sales. These are shown in the table below. All kit part numbers will remain unchanged.

| Description   | Old part number | New part number |
|---------------|-----------------|-----------------|
| PH10M PLUS    | A-5863-1000     | A-5863-4000     |
| PH10T PLUS    | A-5863-2000     | A-5863-5000     |
| PH10MQ PLUS   | A-5863-3000     | A-5863-6000     |
| PH10M-iQ PLUS | A-1025-1800     | A-5863-7000     |

Please see the RBE part number changes on the next page.

If you have any questions or comments on this bulletin please visit www.renishaw.com/cmmsupport and use the 'Email support' facility. This will ensure that your call is logged and processed efficiently.

Page 1 of 2 PBC-02034

For orders of RBE units, new part numbers have been added to the current range of RBE part numbers. The head type being returned (whether non-RoHS compliant or RoHS compliant) will determine which replacement should be ordered for the RBE transaction.

RBE transactions for non-RoHS compliant items being returned to Renishaw can be replaced with the same, non-RoHS compliant version of the product. Please order the correct RBE part number to match the product that is being returned.

## Non-RoHS compliant product

| Description       | Head being returned | Part number to order |
|-------------------|---------------------|----------------------|
| PH10M PLUS RBE    | A-5863-1000         | A-5863-1000-RBE      |
| PH10T PLUS RBE    | A-5863-2000         | A-5863-2000-RBE      |
| PH10MQ PLUS RBE   | A-5863-3000         | A-5863-3000-RBE      |
| PH10M-iQ PLUS RBE | A-1025-1800         | A-1025-1800-RBE      |
| Legacy PH10M RBE  | A-1025-0050         | A-1025-6050-RBE      |
| Legacy PH10T RBE  | A-1025-1520         | A-1025-7526-RBE      |
| Legacy PH10MQ RBE | A-1036-0001         | A-1036-6001-RBE      |

## RoHS compliant product released in this bulletin

| Description       | Head being returned | Part number to order |
|-------------------|---------------------|----------------------|
| PH10M PLUS RBE    | A-5863-4000         | A-5863-4000-RBE      |
| PH10T PLUS RBE    | A-5863-5000         | A-5863-5000-RBE      |
| PH10MQ PLUS RBE   | A-5863-6000         | A-5863-6000-RBE      |
| PH10M-iQ PLUS RBE | A-5863-7000         | A-5863-7000-RBE      |
| Legacy PH10M RBE  | A-1025-4500         | A-1025-4500-RBE      |
| Legacy PH10T RBE  | A-1025-5500         | A-1025-5500-RBE      |
| Legacy PH10MQ RBE | A-1025-6500         | A-1025-6500-RBE      |

Your local Renishaw subsidiary office will be able to offer guidance for the ordering procedure.

If you have any questions or comments on this bulletin please visit <a href="www.renishaw.com/cmmsupport">www.renishaw.com/cmmsupport</a> and use the 'Email support' facility. This will ensure that your call is logged and processed efficiently.

Page 2 of 2 PBC-02034